

# Material Handling

1926 Subpart H

7/18/2019

Rigging equipment for material handling must be inspected prior to use

Rigging(slings, hooks, etc.) must have permanently affixed and legible identification markings as prescribed by the manufacturer that indicate the recommended safe working load.

Rigging is not to be used without affixed, legible identification markings

Welded alloy steel chain slings must have permanently affixed durable identification stating size, grade, rated capacity, and sling manufacturer.

Protruding ends of strands in splices on slings and bridles must be covered or blunted.

A sling must not be pulled from under a load when the load is resting on the sling.

Wire rope slings must have permanently affixed, legible identification markings stating size, rated capacity for the type(s) of hitch(es) used and the angle upon which it is based, and the number of legs if more than one.

Each synthetic web sling must be marked or coded to show: name or trademark of manufacturer, rated capacities for the type of hitch, and the type of material.